
Poznan 213, basset, W + crown
Poznan 213, trace 1
Poznan 213, trace 2
Poznan 213, tone holes
The contraction at this part of the bore is caused by a sleeve inserted to attach the foot joint to the body. It is almost certainly a later repair.
Bore diameter in mm
Length from top in mm